





- Parts list -

<b>Mode</b>	MD mode	<b>Mod. des. overview</b>	SLK ROADSTER
<b>FIN/MD</b>	WDB 1714561F096975	<b>Catalog</b>	66V
<b>VIN</b>	WDBWK56F46F096975	<b>Major assembly:</b>	
<b>Sales designation</b>	SLK 350	<b>Major assembly MD</b>	
<b>Assortment class</b>	Car	<b>Group</b>	82 - ELECTRICAL SYSTEM
<b>Market</b>	North America	<b>Subgroup</b>	175 - FRONT LIGHTING

Item no.	Part number	Designation/description	Quantity	Version
10	A 171 820 35 61	<b>LIGHTING UNIT</b> LEFT Code: 494	001	
10	A 171 820 36 61	<b>LIGHTING UNIT</b> RIGHT Code: 494	001	
60	A 000 826 00 29	. <b>HOSE</b> LIGHTING UNIT VENTILATION	008	
70	N 000000 000853	. <b>BULB</b> STANDING LAMP AND PARKING LAMP 12V-5W	001	
80	A 001 826 35 82	. <b>LAMP HOLDER</b> STANDING LAMP AND PARKING LAMP	002	
90	N 000000 003138	. <b>BULB</b> BLINKER LIGHT 12.8V-30/2.2CP Code: 494	002	
100	A 001 826 42 82	. <b>LAMP SOCKET</b> BLINKER LIGHT Code: 494	001	
110	N 400809 000007	. <b>BULB</b> LOW BEAM H7 12V-55W	002	
110	N 400809 000007	. <b>BULB</b> HIGH BEAM H7 12V-55W	002	
130	A 001 826 33 82	. <b>LAMP SOCKET</b> LOW BEAM Code: -614-618	002	
130	A 001 826 36 82	. <b>LAMP SOCKET</b> HIGH BEAM	002	
160	A 000 826 43 24	. <b>PROTECTIVE COWL</b> LOW BEAM	002	
170	A 001 826 01 24	. <b>COVER</b> HIGH BEAM	002	
180	A 171 820 55 26	<b>CONTROL UNIT</b> LIGHT SENSOR	001	
190	A 000 991 07 70	<b>SPRING CLAMP</b> MOUNTING, RAIN/LIGHT SENSOR	001	
200	N 304017 005011	<b>HEXAGON HEAD BOLT</b> HEADLAMP TO FENDER M5X20	004	
210	N 000931 005022	<b>SCREW</b> LAMP UNIT TO MULTIPLE SUPPORT M5 X 35	002	
220	A 004 994 12 45	<b>SPRING NUT</b> LAMP UNIT TO MULTIPLE SUPPORT M5	002	
290	A 171 820 05 14	<b>BRACKET</b> REPAIR SOLUTION FOR HEADLAMPS LEFT	001	
290	A 171 820 06 14	<b>BRACKET</b> REPAIR SOLUTION FOR HEADLAMPS RIGHT	001	
300	A 203 820 03 59	<b>FOGLAMP</b> LEFT Code: -772  [033] From Chassis: F 096174 From Date: 31/08/2005	001	

300	A 203 820 00 59	<b>FOGLAMP</b> RIGHT Code: -772  [033] From Chassis: F 096174 From Date: 31/08/2005	001
310	A 203 826 01 90	. <b>LENS</b> LEFT FOGLAMP Code: -772/-619	001
310	A 203 826 02 90	. <b>LENS</b> RIGHT FOGLAMP Code: -772/-619	001
320	A 215 826 01 91	. <b>SEAL RING</b> LENS TO HOUSING Code: -772	002
330	A 140 826 02 84	. <b>SPRING</b> LENS TO HOUSING Code: -772	006
340	N 000000 008137	. <b>BULB</b> FOGLAMP 12V-55W Code: -772	002
350	N 000000 000535	<b>TAPPING SCREW</b> FOGLAMP TO BRACKET 4.8X13  [002] To Chassis: F 197201 To Date: 31/03/2008 Excep...	002
350	N 000000 001454	<b>TAPPING SCREW</b> FOGLAMP TO BRACKET 4.8X19  [002] To Chassis: F 197201 To Date: 31/03/2008 Excep...	002
360	A 001 990 75 91	<b>SHEET METAL NUT</b> FOGLAMP TO BRACKET	004
370	A 171 820 01 21	<b>BLINKER LAMP</b> IN PROTECTIVE STRIP, LEFT Code: 264	001
370	A 171 820 02 21	<b>BLINKER LAMP</b> IN PROTECTIVE STRIP, RIGHT Code: 264	001
390	N 000000 000853	<b>BULB</b> SIDE MARKER LAMP IN BUMPER 12V-5W Code: 494	002
400	A 000 540 09 66	<b>LAMP HOLDER</b> SIDE MARKER LAMPS E6/3-E6/4	002
900	A 036 545 59 28	<b>CLUTCH</b> FOG LAMPS, LEFT AND RIGHT 2-PIN SLK 2.8;E5/1-E5/2	002
900	A 168 545 25 28	<b>PIN BUSHING HOUSING</b> LAMP UNIT LEFT AND RIGHT 3-PIN;SLK2.8;E1/E2	002
900	A 036 545 59 28	<b>CLUTCH</b> LAMP UNIT LEFT AND RIGHT 2-PIN SLK 2.8;E1/E2 ;CODE B	002
900	A 168 545 29 28	<b>RECEPTACLE HOUSING</b> LAMP UNIT LEFT AND RIGHT 2-PIN SLK2.8;E1/E2 ;CODE A	002
900	A 000 153 08 42	<b>FEM. CONNECTOR HOUS., EL.</b> LAMP UNIT LEFT AND RIGHT 4-PIN SLK2.8;E1/E2	002
901	A 009 545 82 26	<b>FEMALE CONTACT</b> 1.5-2.5 MM2 SLK2.8	NB
901	A 009 545 81 26	<b>FEMALE CONTACT</b> 0.75-1.0 MM2 SLK2.8	NB
902	A 220 545 19 28	<b>CLUTCH</b> HEADLAMP RANGE ADJUSTMENT CONTROLUNIT, 20-PIN 20 PIN MQS;N71	001
903	A 016 545 41 26	<b>FEMALE CONTACT</b> HEADLAMP RANGE ADJUSTMENT CONTROLUNIT, 20-PIN 0.25-0.5 MM2 MQS;N71	NB
904	A 029 545 55 28	<b>PIN BUSHING HOUSING</b> RAIN AND LIGHT SENSOR 3-PIN MQS;B38/2	001

